



**Masco Service Corp.  
Repair Station No.:  
UX2D230L**

**Capability List  
Limited Radio  
Revision: 12  
Date: 03/10/2020**

OEM	MODEL	PART NUMBER	NOMENCLATURE	LIMITATION	ADDED
HONEYWELL	TRACKER II	1616-050-01A	TRANSCEIVER	OVERHAUL /REPAIR	09/22/14
HONEYWELL	TRACKER II	1616-050-02A	TRANSCEIVER	OVERHAUL /REPAIR	09/22/14
HONEYWELL	TRACKER II	1616-050-03A	TRANSCEIVER	OVERHAUL /REPAIR	09/22/14
HONEYWELL	TRACKER II	1616-050-04A	TRANSCEIVER	OVERHAUL /REPAIR	09/22/14
HONEYWELL	TRACKER II	1616-050-05A	TRANSCEIVER	OVERHAUL /REPAIR	09/22/14
HONEYWELL	TRACKER III	1616-050-13	TRANSCEIVER	OVERHAUL /REPAIR	09/22/14
HONEYWELL	DIALER SOP 11	1616-052-00	DIALER	OVERHAUL /REPAIR	09/22/14
HONEYWELL	DIALER SOP 11- Night Vision LED	1616-052-02	DIALER	OVERHAUL /REPAIR	09/22/14
HONEYWELL	MMU II	1616-055-10	MMU II	OVERHAUL /REPAIR	09/22/14
HONEYWELL	MMU II-Night Vision Compatible	1616-055-12	MMU II	OVERHAUL /REPAIR	09/22/14
HONEYWELL	POTS Transceiver	1616-400-01A	TRANSCEIVER	OVERHAUL /REPAIR	09/22/14
DEKLIN TECH.	Deklin Handset	1616-410-00	HANDSET	FUNCTION CHECK ONLY	09/22/14
HONEYWELL	ARINC 429 Converter	1616-429-01	CONVERTER	OVERHAUL /REPAIR	09/22/14
HONEYWELL	Tracker II-POTS Transceiver	1616-450-01A	TRANSCEIVER	OVERHAUL /REPAIR	09/22/14


**\*BOLD TYPE INDICATES CURRENT REVISION ADDITION(S)**

OEM	MODEL	PART NUMBER	NOMENCLATURE	LIMITATION	ADDED
HONEYWELL	Tracker II-POTS Transceiver	1616-450-02A	TRANSCEIVER	OVERHAUL /REPAIR	09/22/14
HONEYWELL	Tracker II-POTS Transceiver	1616-450-13	TRANSCEIVER	OVERHAUL /REPAIR	09/22/14
HONEYWELL	CONFIGURATION / SIM MODULE	1616-905-01	CONFIG/SIM MODULE (ICSM)	FUNCTION CHECK ONLY	01/13/15
HONEYWELL	CONFIGURATION / SIM MODULE	1616-905-02	CONFIG/SIM MODULE (ICSM)	FUNCTION CHECK ONLY	01/13/15
HONEYWELL	ANTENNA	1616-880-01	ANTENNA	FUNCTION CHECK ONLY	11/11/15
HONEYWELL	ANTENNA	1616-880-02	ANTENNA	FUNCTION CHECK ONLY	11/11/15
HONEYWELL	ANTENNA	1616-880-13	ANTENNA	FUNCTION CHECK ONLY	03/03/16
HONEYWELL	ANTENNA	1616-880-04	ANTENNA	FUNCTION CHECK ONLY	03/03/16
HONEYWELL	ANTENNA	1616-880-00	ANTENNA	FUNCTION CHECK ONLY	05/05/17
HONEYWELL	KX 155A	069-1032- ( )	NAV/COM TRANSCEIVER	OVERHAUL	05/05/17
HONEYWELL	KX 155/165	069-1024-( ) 069-1025-( )	VHF NAV/COM TRANSCEIVER	OVERHAUL	05/05/17
HONEYWELL	KY 196/197	064-1019-( ) 064-1021-( )	VHF COMM TRANSCEIVER	OVERHAUL	05/05/17
HONEYWELL	KY 196A/197A	064-1053-( ) 064-1054-( )	VHF COMM TRANSCEIVER	OVERHAUL	05/05/17
HONEYWELL	KY 196B	064-1084-( )	VHF COMM TRANSCEIVER	OVERHAUL	05/05/17
HONEYWELL	KY 96A/97A	064-1051-( ) 064-1052-( )	VHF COMM TRANSCEIVER	OVERHAUL	05/05/17
<b>*BOLD TYPE INDICATES CURRENT REVISION ADDITION(S)</b>					

OEM	MODEL	PART NUMBER	NOMENCLATURE	LIMITATION	ADDED
HONEYWELL	ANTENNA	1616-880-14	ANTENNA	FUNCTION CHECK ONLY	03/01/19
HONEYWELL	ANTENNA	1616-880-22	ANTENNA	FUNCTION CHECK ONLY	03/01/19
HONEYWELL	SKY CONNECT / TRACKER	1616-105-01	TRAY	FUNCTION CHECK ONLY	07/15/19
APPAREO	VISION 1000	150575-000010	CAMERA	FUNTION CHECK ONLY	08/13/19
APPAREO	VISION 1000	150575-000011	CAMERA	FUNTION CHECK ONLY	08/13/19
APPAREO	VISION 1000	150575-000014	CAMERA	FUNTION CHECK ONLY	08/13/19
APPAREO	VISION 1000	150575-000016	CAMERA	FUNTION CHECK ONLY	08/13/19
APPAREO	VISION 1000	150575-000021	CAMERA	FUNTION CHECK ONLY	08/13/19
GARMIN	GTX330	011-00455-00	TRANSPONDER	REPAIR	12/10/19
GARMIN	GTX330	011-00455-20	TRANSPONDER	REPAIR	12/10/19
GARMIN	GTX330ES	011-00455-60	TRANSPONDER	REPAIR	12/10/19
GARMIN	GTX330ES	011-00455-80	TRANSPONDER	REPAIR	12/10/19
GARMIN	GPS 400W	011-01057-SERIES	NAV/COMM TRANSCEIVER	REPAIR	02/19/20
GARMIN	GNC 420W	011-01058-SERIES	NAV/COMM TRANSCEIVER	REPAIR	02/19/20
GARMIN	GNC 420AW	011-01059-SERIES	NAV/COMM TRANSCEIVER	REPAIR	02/19/20

GARMIN	GNS 430W	011-01060-SERIES	NAV/COMM TRANSCEIVER	REPAIR	02/19/20
GARMIN	GNS 430AW	011-01061-SERIES	NAV/COMM TRANSCEIVER	REPAIR	02/19/20
GARMIN	GPS 500W	011-01062-SERIES	NAV/COMM TRANSCEIVER	REPAIR	02/19/20
GARMIN	GNS 530W	011-01064-SERIES	NAV/COMM TRANSCEIVER	REPAIR	02/19/20
GARMIN	GNS 530AW	011-01066-SERIES	NAV/COMM TRANSCEIVER	REPAIR	02/19/20
HONEYWELL	TRACKER 3A	1616-050-23	TRANSCEIVER	OVERHAUL	02/19/20
<b>GARMIN</b>	<b>GNS 430</b>	<b>011-00280-SERIES</b>	<b>NAV/COM TRANSCEIVER</b>	<b>REPAIR</b>	<b>03/10/20</b>
<b>GARMIN</b>	<b>GNS 430A</b>	<b>011-00836-SERIES</b>	<b>NAV/COM TRANSCEIVER</b>	<b>REPAIR</b>	<b>03/10/20</b>
<b>GARMIN</b>	<b>GMX 200</b>	<b>011-01271-SERIES</b>	<b>MULTI FUNCTION DISPLAY</b>	<b>REPAIR</b>	<b>03/10/20</b>
<b>GARMIN</b>	<b>GMX 200 I/O TRAFFIC</b>	<b>011-01465-SERIES</b>	<b>MULTI FUNCTION DISPLAY</b>	<b>REPAIR</b>	<b>03/10/20</b>
<b>GARMIN</b>	<b>GMX 200 I/O RADAR/TAWS</b>	<b>011-01466-SERIES</b>	<b>MULTI FUNCTION DISPLAY</b>	<b>REPAIR</b>	<b>03/10/20</b>
<b>GARMIN</b>	<b>GMX 200 I/O TRAFFIC/RADAR</b>	<b>011-01467-SERIES</b>	<b>MULTI FUNCTION DISPLAY</b>	<b>REPAIR</b>	<b>03/10/20</b>

**\*BOLD TYPE INDICATES CURRENT REVISION ADDITION(S)**


  
 APPROVED BY / TITLE Quality Manager 10 MAR 2020
  
 DATE