




Masco Service Corp.
Repair Station No.:
UX2D230L

Capability List
Limited Radio
Revision: 20
Date: 06/20/2023

OEM	MODEL	PART NUMBER	NOMENCLATURE	LIMITATION	ADDED
Honeywell	Tracker II	1616-050-()	Transceiver	MRO	09/22/14
Honeywell	Tracker III	1616-050-13	Transceiver	MRO	09/22/14
Honeywell	Dialer, SOP 11	1616-052-()	Dialer	MRO	09/22/14
Honeywell	MMU II	1616-055-()	Mission Mgmt	MRO	09/22/14
Honeywell	POTS, Tracker	1616-400-01A	Transceiver	MRO	09/22/14
Deklin	Forte Handset	1616-410-00	Handset	Test	09/22/14
Honeywell	ARINC 429	1616-429-01	Converter	MRO	09/22/14
Honeywell	POTS, Tracker II	1616-450-()	Transceiver	MRO	09/22/14
Honeywell	POTS, Tracker III	1616-450-13	Transceiver	MRO	09/22/14
Honeywell	ICSM	1616-905-()	Config. Module	Test	01/13/15
Honeywell	Antenna	1616-880-01	Antenna	Test	11/11/15
Honeywell	Antenna	1616-880-13	Antenna	Test	03/03/16
Honeywell	Antenna	1616-880-04	Antenna	Test	03/03/16
Honeywell	Antenna	1616-880-00	Antenna	Test	05/05/17
Honeywell	KX 155A	069-1032-()	Nav/Comm Trans	MRO	05/05/17
Honeywell	KX 155	069-1024-()	Nav/Comm Trans	MRO	05/05/17
Honeywell	KX 165	069-1025-()	Nav/Comm Trans	MRO	05/05/17
Honeywell	KY 196	064-1019-()	VHF Comm Trans	MRO	05/05/17
Honeywell	KY 197	064-1021-()	VHF Comm Trans	MRO	05/05/17
Honeywell	KY 197A	064-1053-()	VHF Comm Trans	MRO	05/05/17
Honeywell	KY 196A	064-1054-()	VHF Comm Trans	MRO	05/05/17
Honeywell	KY 196B	064-1084-()	VHF Comm Trans	MRO	05/05/17
Honeywell	KY 96A	064-1052-()	VHF Comm Trans	MRO	05/05/17
Honeywell	KY 97A	064-1051-()	VHF Comm Trans	MRO	05/05/17
Honeywell	Antenna	1616-880-14	Antenna	Test	03/01/19
Honeywell	Antenna	1616-880-22	Antenna	Test	03/01/19
Honeywell	Tracker, Tray	1616-105-01	Tray	Test	07/15/19
Garmin	GTX 330	011-00455-()	Transponder	Repair	12/10/19
Garmin	GPS 400W	011-01057-()	Nav/Comm Trans	Repair	02/19/20
Garmin	GNC 420W	011-01058-()	Nav/Comm Trans	Repair	02/19/20
Garmin	GNC 420AW	011-01059-()	Nav/Comm Trans	Repair	02/19/20
Garmin	GNS 430W	011-01060-()	Nav/Comm Trans	Repair	02/19/20
Garmin	GNS 430AW	011-01061-()	Nav/Comm Trans	Repair	02/19/20
Garmin	GPS 500W	011-01062-()	Nav/Comm Trans	Repair	02/19/20
Garmin	GNS 530W	011-01064-()	Nav/Comm Trans	Repair	02/19/20
Garmin	GNS 530AW	011-01066-()	Nav/Comm Trans	Repair	02/19/20

****BOLD TYPE INDICATES CURRENT REVISION ADDITION(S)**

OEM	MODEL	PART NUMBER	NOMENCLATURE	LIMITATION	ADDED
Honeywell	Tracker III A	1616-050-23	Transceiver	MRO	02/19/20
Garmin	GNS 430	011-00280-()	Nav/Comm Trans	Repair	03/10/20
Garmin	GNS 430A	011-00836-()	Nav/Comm Trans	Repair	03/10/20
Garmin	GMX 200	011-01271-()	Function Display	Repair	03/10/20
Garmin	GMX 200 Traffic	011-01465-()	Function Display	Repair	03/10/20
Garmin	GMX 200 Radar	011-01466-()	Function Display	Repair	03/10/20
Garmin	GMX 200 Traf/Rad	011-01467-()	Function Display	Repair	03/10/20
Garmin	GPS 500W TAWS	011-01063-()	Nav/Comm Trans	Repair	04/03/20
Garmin	GNS 530W TAWS	011-01065-()	Nav/Comm Trans	Repair	04/03/20
Garmin	GNS 530AW TAWS	011-01067-()	Nav/Comm Trans	Repair	04/03/20
Honeywell	MCT	1616-062-22	Comm Terminal	MRO	01/21/21
Garmin	GTN 625	011-02254-00	GPS	Repair	05/04/21
Garmin	GTN 635	011-02255-00	GPS VHF Comm	Repair	05/04/21
Garmin	GTN 650	011-02256-()	GPS VHF Comm Nav	Repair	05/04/21
Honeywell	ICSM	1616-900-62	Config Module	Repair	09/16/21
Appareo	Vision 1000	150575-()	Camera	Repair	09/16/21
Honeywell	MMU	1616-055-()	Mission Mgmt	Test	10/19/21
Appareo	Vision 1000	153070-()	Camera	Repair	06/08/22
Garmin	GPS 500	011-00562-()	GPS	Repair	10/19/22
Garmin	GPS 500TAWs	011-00863-()	GPS	Repair	10/19/22
Honeywell	KLN 900 GPS Nav	066-04034-()	GPS	MRO	06/20/23
**BOLD TYPE INDICATES CURRENT REVISION ADDITION(S)					



 APPROVED BY / TITLE

20 June 2023

 DATE